



State of New Hampshire  
DEPARTMENT OF ENVIRONMENTAL SERVICES

6 Hazen Drive, P.O. Box 95, Concord, NH 03302-0095

(603) 271-3406 FAX (603) 271-7894



October 8, 2003  
Letter of Compliance  
For  
Letter of Deficiency

Mr. Corey Smith  
Waterville Estates Association  
1 Village Center  
Box 36WE  
Campton, NH 03223

Re: Locke II Dam #035.13, Campton  
Letter of Deficiency (LOD) Dam #035.13  
Issued on April 25, 2002

Dear Mr. Smith

Based on a file review and a follow-up inspection conducted on September 18, 2003 of the above referenced dam, the Department of Environmental Services (DES) has determined that the referenced LOD is considered complete and will be closed. Enclosed is a copy for your reference.

DES would like to commend you on a job well done. As a reminder DES recommends maintaining the brush on an annual basis. We also recommend that you keep a bi-weekly log of the noted seepage.

If you have any questions or comments, please contact me at 603-271-3406 or write to the Water Division at 29 Hazen Drive, P.O. Box 95, Concord, NH 03302-0095.

Sincerely,

**COPY**

Dale F. Guinn, P.E.  
Dam Safety Engineer

Enclosure: Copy of April 25, 2002 LOD

cc: Gretchen Rule ✓  
Town of Campton

DFG/h:/safety/wendy/lod/03513compltr.doc



**State of New Hampshire**  
**DEPARTMENT OF ENVIRONMENTAL SERVICES**

6 Hazen Drive, P.O. Box 95, Concord, NH 03302-0095  
(603) 271-3406 FAX (603) 271-7894



April 15, 2003

Mr. Corey Smith  
Waterville Estates Association  
1 Village Center  
Box 36WE  
Campton, NH 03223

Re: Letter of Deficiency (LOD), Dated April 25, 2002  
Locke 1 Dam #035.12-Campton

Dear Mr. Smith:

Based on a follow-up inspection made to the above referenced dam on October 24, 2002, the Department of Environmental Services (DES) has determined that the deficiencies relative to Dam #035.12, as outlined in the above referenced LOD, have been corrected. DES will be conducting another follow-up inspection to verify completion of the deficiencies relative to Dam #035.13, also outlined in the same LOD. DES will advise you of the compliance status upon completion of the inspection. DES appreciates your cooperation in this matter. The next routine inspection of this dam is scheduled for the 2008 inspection season.

DES is requesting that you monitor the failed section for further settlement, due to a limited compaction effort as was indicated. If settlement is observed, repairs should be conducted immediately to fill the area with properly compacted material.

If you have any questions or comments, please contact me at 271-3406 or write to the Water Division at the address listed above.

Sincerely,

**COPY**

Dale F. Guinn, P.E.  
Dam Safety Engineer

cc: Town of Campton  
DFG/was/h:/safety/wendy/ltr/smithcltr.doc